Oil Field Environmental Incident Summary

Responsible Party: OASIS PETROLEUM NORTH AMERICA LLC **Well Operator:** OASIS PETROLEUM NORTH AMERICA LLC

Well Name: HOLMES 5601 32-29 CTB

Field Name: TYRONE Well File #:

Date Incident:1/21/2016Time Incident:11:00Facility ID Number:219167-01County:WILLIAMSTwp:156Rng:101Sec:32Qtr:SE SE

Location Description:

Submitted By: Luke Radke Received By:

Contact Person: Luke Radke

1001 FANNIN STE 1500 HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 1 Barrels 1 Barrels 1 barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 3/7/2016 Clean Up Concluded: 1/22/2016

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Keep separator dumps clear

Wastes Disposal Location: Tanks onsite

Agencies Involved:

Updates

Date: 1/26/2016 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.